



Pre-delivery Inspection Checklist

KU68ZTD / 3 Feb 2024 / Ford transit

Complete

Score	106 / 107 (99.07%)	Flagged items	0	Actions	0
--------------	--------------------	----------------------	---	----------------	---

Car Make/Model

Ford transit

Vehicle Identification Number

KU68ZTD

Dealer

Reeds motors ltd

Location

86 Welley Road
Staines-Upon-Thames
England
TW19 5EP
United Kingdom
(51.46272551788299,
-0.5614601463432015)

Conducted on

03.02.2024 09:32 GMT

Take photos of the vehicle from all sides



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5

Odometer & chase number

Odometer reading

94430

chase number or photo



Photo 6

Body Exterior

6 / 6 (100%)

Glass

Safe

Door locks/operation

Pass

Fuel filler cover/petrol cap

Pass

General bodywork condition

very good

Corrosion

Pass

Outside mirrors

Pass




Photo 7




Photo 8

Wheels & Tires AND Brakes

12 / 12 (100%)

Front right tire

very good

Over 7mm




Photo 9




Photo 10



Photo 11



Photo 12

Front left tire

very good

Over 7mm




Photo 13



Photo 14



Photo 15



Photo 16

Rear left tire

very good

Over 8mm



Photo 17



Photo 18



Photo 19

Rear right tire

very good

Over 8 mm



Photo 20



Photo 21



Photo 22

Spare tire

Pass




Photo 23

locking wheel nut

N/A

Discs & pads front

Good

Disc and pad over 70%



Photo 24



Photo 25



Photo 26




Photo 27

Discs & pad or Drums rear

Good

Disc and pad over 50%




Photo 28



Photo 29




Photo 30

Fluid leaks

Pass

Caliper and Wheel Cylinders

Pass

Pipes/unions & connections

Pass

Hand brake operation/adjustments

very good

Interior & Luggage Compartment

7 / 7 (100%)

Seat mechanism & Folding seats

Safe

Electrically Operated seats

N/A

Seat belts

Safe

Heated seats

N/A

Internal mirrors

N/A

Boot/tailgate lock

Safe

sun visor

Safe

Electrical Controls

15 / 15 (100%)

Ignition lock/starting system

Pass




Photo 31

Headlights



Photo 32



Photo 33




Photo 34

Pass

Side lights/running lights



Photo 35



Photo 36

Pass

Brake lights



Photo 37



Photo 38



Photo 39



Photo 40

Pass

Indicator & hazard lights

Pass

Reverse & fog lights

Pass

radio& CD player

Pass



Photo 41

Navigation System

Pass




Photo 42

Panel lights/dashboard illumination

Pass

Switches & controls

Pass

Instrument/controls function

Pass




Horn	Pass
Windows & sunroof operation	Pass
Wipers & jet washers	very good
Alarm & theft-Deterrent System	Pass
HEAT/VENT/AC/DEFOG/DEFROST	3 / 3 (100%)
Air Conditioning system	Yes
Heated system	Yes
Defog/Defrost	Yes
Engine Compartment	17 / 17 (100%)
Coolant level	Pass
	
Photo 43	
Brake fluid level	Pass
	
Photo 44	
	
Photo 45	
Engine oil level	Pass
Clutch fluid level	N/A
Power steering fluid level	Pass
Washer Fluid	Pass
Radiator & cap	Safe
Coolant leaks	Pass



Photo 46



Photo 47



Photo 48




Photo 49

Hoses & pipes

Pass

Water pump

Pass

External engine leaks

Pass



Photo 50



Photo 51




Photo 52




Photo 53




Photo 54




Photo 55



Photo 56

Turbo/supercharger

Pass

Fuel pump & pipes

Safe

Drive belts

Pass

Cold starting

very good

Noise level when engine cold

very good

Excess fumes/smoke

Pass

Clutch & Transmission

5 / 5 (100%)

Fluid/oil leaks

Pass

Linkages (check for signs of wear)

Pass

Clutch test manual gearbox only

Pass

Automatic gear selection test

N/A

Bearings & supports

Pass

all gear selection test 1 / 1 (100%)

Yes

Exhaust System 4 / 4 (100%)

manifold Pass




Photo 57

Heat shields & mountings Pass



Photo 58



Photo 59



Photo 60



Photo 61



Photo 62

Catalytic converter Pass

Overall system condition Pass

Fuel System 4 / 4 (100%)

Fuel Pump Noise Normal Pass

Fuel Pump Pressure Pass

Fuel Filter Pass

Evidence of leaks Pass

Suspension, Underframe & Steering 13 / 13 (100%)

Engine underside leaks Pass




Photo 63




















Photo 64

Steering joints & ball joints Pass

Steering rack Pass

Chassis members	Pass				
Power steering Pump	Pass				
Wheels, hubs & bearings	Pass				
Springs & suspension unit	Pass				
Front suspension & Bushes overall	very good				
     					
Photo 65	Photo 66	Photo 67	Photo 68	Photo 69	Photo 70
Rear Suspension & bushes overall	very good				
 					
Photo 71	Photo 72				
Gaiters	Pass				
Sub frames & mountings	Pass				
Suspension arms, mountings & fixings	Pass				
Tie bars & anti-roll bars	Pass				
Road Test	15 / 15 (100%)				
Road Test 1	15 / 15 (100%)				
Engine - performance	very good				
Engine - noise	Safe				
Engine - excessive fumes or smoke	Pass				
Evidence of overheating	Pass				
Gearbox operation & noise level	Pass				
Final drive operation & noise level	Pass				

Clutch operation	Pass
Cooling fan operation	Pass
Instruments & controls functioning	Pass
General steering & handling	very good
Footbrake operation	Pass
Hand brake operation	Safe
Suspension noise	Pass
Road holding stability	Pass
Warning lights	Pass
Convenience	4 / 5 (80%)
Owners manual	Pass
 <p>Photo 73</p>	
Service book & history	Yes
      <p>Photo 74 Photo 75 Photo 76 Photo 77 Photo 78 Photo 79</p>	
Keys remote controls & spare key	Yes
 <p>Photo 80</p>	
overall condition	1 / 2 (50%)
diagnostic report	1 / 1 (100%)

Pass

Completion

Additional Observations

Test drive for 10 minutes and
speed up to 70 mph

Name & Signature of Vehicle Inspector



M and k
03.02.2024 10:12 GMT