



Pre-delivery Inspection Checklist

LC18 EBU / 2 Feb 2024 / Citroen dispatch

Complete

Score	107 / 107 (100%)	Flagged items	0	Actions	0
Car Make/Model	Citroen dispatch				
Vehicle Identification Number	LC18 EBU				
Dealer	Reeds motors ltd				
Location	(51.46231052900931, -0.5615808015887911)				
Conducted on	02.02.2024 13:29 GMT				

Take photos of the vehicle from all sides



Photo 1



Photo 2



Photo 3



Photo 4




Photo 5

Odometer & chase number

Odometer reading

74642



Photo 6

chase number or photo



Photo 7



Photo 8

Body Exterior

6 / 6 (100%)

Glass

Safe

Door locks/operation

Pass

Fuel filler cover/petrol cap

Pass



Photo 9

General bodywork condition

very good

Corrosion

Pass

Outside mirrors

Pass




Photo 10



Photo 11

Wheels & Tires AND Brakes

12 / 12 (100%)

Front right tire

excellent

Over 8mm



Photo 12



Photo 13



Photo 14



Photo 15



Photo 16

Front left tire

excellent

Over 8mm



Photo 17



Photo 18




Photo 19




Photo 20

Rear left tire

very good

Over 6.5mm




Photo 21




Photo 22




Photo 23




Photo 24

Rear right tire

Good

Over 4mm side side Parsh




Photo 25




Photo 26



Photo 27

Spare tire

Pass




Photo 28

locking wheel nut

N/A

Discs & pads front

Good

Over 75%




Photo 29




Photo 30



Photo 31




Photo 32

Discs & pad or Drums rear

Good

Over 50%




Photo 33




Photo 34



Photo 35

Fluid leaks

Pass

Caliper and Wheel Cylinders

Pass

Pipes/unions & connections

Pass

Hand brake operation/adjustments

very good

Interior & Luggage Compartment

7 / 7 (100%)

Seat mechanism & Folding seats

Safe

Electrically Operated seats

N/A

Seat belts

Safe



Photo 36



Photo 37

Heated seats

N/A

Internal mirrors

Safe



Photo 38

Boot/tailgate lock

Safe

sun visor

Safe

Electrical Controls

15 / 15 (100%)

Ignition lock/starting system

Pass



Photo 39

Headlights

Pass



Photo 40



Photo 41

Side lights/running lights

Pass




Photo 42



Photo 43

Brake lights

Pass



Photo 44



Photo 45




Photo 46



Photo 47



























Photo 48









Indicator & hazard lights

Pass

Reverse & fog lights	Pass
radio& CD player	Pass
	
Photo 49	
Navigation System	N/A
Panel lights/dashboard illumination	Pass
Switches & controls	Pass
Instrument/controls function	Pass
Horn	Pass
Windows & sunroof operation	Pass
Wipers & jet washers	very good
Alarm & theft-Deterrent System	Pass
HEAT/VENT/AC/DEFOG/DEFROST	3 / 3 (100%)
Air Conditioning system	Yes
Heated system	Yes
Defog/Defrost	Yes
Engine Compartment	17 / 17 (100%)
Coolant level	Pass
Brake fluid level	Pass
Engine oil level	Pass
	
Photo 50	

Clutch fluid level	N/A
Power steering fluid level	Pass
 <p>Photo 51</p>	
Washer Fluid	Pass
Radiator & cap	Safe
Coolant leaks	Pass
     <p>Photo 52 Photo 53 Photo 54 Photo 55 Photo 56</p>	
Hoses & pipes	Pass
Water pump	Pass
External engine leaks	Pass
      <p>Photo 57 Photo 58 Photo 59 Photo 60 Photo 61 Photo 62</p>  <p>Photo 63</p>	
Turbo/supercharger	Pass
Fuel pump & pipes	Safe
Drive belts	Pass
Cold starting	very good
Noise level when engine cold	very good

Excess fumes/smoke	Pass
Clutch & Transmission	5 / 5 (100%)
Fluid/oil leaks	Pass
Linkages (check for signs of wear)	Pass
Clutch test manual gearbox only	Pass
Automatic gear selection test	N/A
Bearings & supports	Pass
all gear selection test	1 / 1 (100%)
	Yes
Exhaust System	4 / 4 (100%)
manifold	Pass
	
Photo 64	
Heat shields & mountings	Pass
	
Photo 65	
	
Photo 66	
	
Photo 67	
	
Photo 68	
	
Photo 69	
	
Photo 70	
	
Photo 71	
Catalytic converter	Pass
Overall system condition	Pass
Fuel System	4 / 4 (100%)
Fuel Pump Noise Normal	Pass

Fuel Pump Pressure	Pass
Fuel Filter	Pass
Evidence of leaks	Pass
Suspension, Underframe & Steering	13 / 13 (100%)
Engine underside leaks	Pass
Steering joints & ball joints	Pass
Steering rack	Pass
Chassis members	Pass
Power steering Pump	Pass
Wheels, hubs & bearings	Pass
Springs & suspension unit	Pass
Front suspension & Bushes overall	very good
     	
<p>Photo 72 Photo 73 Photo 74 Photo 75 Photo 76 Photo 77</p>	
Rear Suspension & bushes overall	very good
 	
<p>Photo 78 Photo 79</p>	
Gaiters	Pass
Sub frames & mountings	Pass
Suspension arms, mountings & fixings	Pass
Tie bars & anti-roll bars	Pass
Road Test	15 / 15 (100%)


Road Test 1	15 / 15 (100%)
Engine - performance	very good
Engine - noise	Safe
Engine - excessive fumes or smoke	Pass
Evidence of overheating	Pass
Gearbox operation & noise level	Pass
Final drive operation & noise level	Pass
Clutch operation	Pass
Cooling fan operation	Pass
Instruments & controls functioning	Pass
General steering & handling	very good
Footbrake operation	Pass
Hand brake operation	Safe
Suspension noise	Pass
Road holding stability	Pass
Warning lights	Pass
Convenience	5 / 5 (100%)
Owners manual	Pass
	
Photo 80	
Service book & history	Yes



Photo 81




Photo 82




Photo 83




Photo 84




Photo 85




Photo 86



Photo 87

Keys remote controls & spare key

Yes

2 keys




Photo 88

overall condition

2 / 2 (100%)

very good

diagnostic report

1 / 1 (100%)

Pass

Completion

Additional Observations

Test drive for 10 minutes and speed up to 70 mph

Name & Signature of Vehicle Inspector

M and k
02.02.2024 13:57 GMT