



## Pre-delivery Inspection Checklist

Yo69fmv / 16 Dec 2023 / Ford transit

Complete

Score	107 / 107 (100%)	Flagged items	0	Actions	0
<b>Car Make/Model</b>	Ford transit				
<b>Vehicle Identification Number</b>	Yo69fmv				
<b>Dealer</b>	Reeds motors ltd				
<b>Location</b>	86 Welley Road Staines-Upon-Thames England TW19 5EP United Kingdom (51.46273745474635, -0.5614568056361521)				
<b>Conducted on</b>	16.12.2023 15:28 GMT				

Take photos of the vehicle from all sides



Photo 1



Photo 2



Photo 3



Photo 4

Odometer & chase number

Odometer reading

76238



Photo 5

chase number or photo



Photo 6

Body Exterior

6 / 6 (100%)

Glass

Safe

Door locks/operation

Pass

Fuel filler cover/petrol cap

Pass

General bodywork condition

very good

Corrosion

Pass

Outside mirrors

Pass



Photo 7



Photo 8

Wheels & Tires AND Brakes

12 / 12 (100%)

**Front right tire**

Good

Over 4mm



Photo 9



Photo 10



Photo 11



Photo 12

**Front left tire**

Good

Over 4mm



Photo 13



Photo 14



Photo 15




Photo 16

**Rear left tire**

very good

Over 7mm



Photo 17



Photo 18



Photo 19



Photo 20

**Rear right tire**

very good

Over 8mm




Photo 21



Photo 22



Photo 23




Photo 24



Photo 25

**Spare tire**

Pass



Photo 26

**locking wheel nut**

Pass



Photo 27

**Discs & pads front**

Good

Over 70%



Photo 28



Photo 29



Photo 30




Photo 31

**Discs & pad or Drums rear**

Good

Over 50%



Photo 32




Photo 33



Photo 34




Photo 35

**Fluid leaks**

Pass

**Caliper and Wheel Cylinders**

Pass

**Pipes/unions & connections**

Pass

**Hand brake operation/adjustments**

very good

**Interior & Luggage Compartment**

7 / 7 (100%)

**Seat mechanism & Folding seats**

Safe

**Electrically Operated seats**

Pass

**Seat belts**

Safe

**Heated seats**

Pass













Photo 36

<b>Internal mirrors</b>	N/A
<b>Boot/tailgate lock</b>	Safe
<b>sun visor</b>	Safe
Electrical Controls	15 / 15 (100%)
<b>Ignition lock/starting system</b>	Pass
 <p>Photo 37</p>	
<b>Headlights</b>	Pass
   <p>Photo 38      Photo 39      Photo 40</p>	
<b>Side lights/running lights</b>	Pass
  <p>Photo 41      Photo 42</p>	
<b>Brake lights</b>	Pass
<b>Indicator &amp; hazard lights</b>	Pass
  <p>Photo 43      Photo 44</p>	
<b>Reverse &amp; fog lights</b>	Pass
 <p>Photo 45</p>	

radio& CD player

Pass




Photo 46

Navigation System

N/A

Panel lights/dashboard illumination

Pass

Switches & controls

Pass




Photo 47



Photo 48



Photo 49



Photo 50



Photo 51



Photo 52

Instrument/controls function

Pass

Horn

Pass

Windows & sunroof operation

Pass

Wipers & jet washers

very good

Alarm & theft-Deterrent System

Pass

HEAT/VENT/AC/DEFOG/DEFROST

3 / 3 (100%)

Air Conditioning system

Yes

Heated system

Yes

Defog/Defrost

Yes

Engine Compartment

17 / 17 (100%)

Coolant level

Pass



Photo 53



Photo 54

Brake fluid level

Pass



Photo 55

**Engine oil level**

Pass




Photo 56

**Clutch fluid level**

N/A

**Power steering fluid level**

N/A

**Washer Fluid**

Pass

**Radiator & cap**

Safe

**Coolant leaks**

Pass

**Hoses & pipes**

Pass

**Water pump**

Pass

**External engine leaks**

Pass




Photo 57



Photo 58



Photo 59




Photo 60




Photo 61




Photo 62




Photo 63

**Turbo/supercharger**

Pass

**Fuel pump & pipes**


Safe

**Drive belts**

Pass

**Cold starting**

very good

<b>Noise level when engine cold</b>	very good
<b>Excess fumes/smoke</b>	Pass
Clutch & Transmission	5 / 5 (100%)
<b>Fluid/oil leaks</b>	Pass
<b>Linkages (check for signs of wear)</b>	Pass
<b>Clutch test manual gearbox only</b>	Pass
<b>Automatic gear selection test</b>	N/A
<b>Bearings &amp; supports</b>	Pass
all gear selection test	1 / 1 (100%)
	Yes
Exhaust System	4 / 4 (100%)
<b>manifold</b>	Pass
	
Photo 64	
<b>Heat shields &amp; mountings</b>	Pass
<b>Catalytic converter</b>	Pass
<b>Overall system condition</b>	Pass
Fuel System	4 / 4 (100%)
<b>Fuel Pump Noise Normal</b>	Pass
<b>Fuel Pump Pressure</b>	Pass
<b>Fuel Filter</b>	Pass
<b>Evidence of leaks</b>	Pass
Suspension, Underframe & Steering	13 / 13 (100%)
<b>Engine underside leaks</b>	Pass

















Photo 65

<b>Steering joints &amp; ball joints</b>	Pass
<b>Steering rack</b>	Pass
<b>Chassis members</b>	Pass
<b>Power steering Pump</b>	Pass
<b>Wheels, hubs &amp; bearings</b>	Pass
<b>Springs &amp; suspension unit</b>	Pass
<b>Front suspension &amp; Bushes overall</b>	very good
     	
<p>Photo 66      Photo 67      Photo 68      Photo 69      Photo 70      Photo 71</p>	
<b>Rear Suspension &amp; bushes overall</b>	Good
 	
<p>Photo 72      Photo 73</p>	
<b>Gaiters</b>	Pass
<b>Sub frames &amp; mountings</b>	Pass
<b>Suspension arms, mountings &amp; fixings</b>	Pass
<b>Tie bars &amp; anti-roll bars</b>	Pass
Road Test	15 / 15 (100%)
Road Test 1	15 / 15 (100%)
<b>Engine - performance</b>	very good

Engine - noise	Safe
Engine - excessive fumes or smoke	Pass
Evidence of overheating	Pass
Gearbox operation & noise level	Pass
Final drive operation & noise level	Pass
Clutch operation	Pass
Cooling fan operation	Pass
Instruments & controls functioning	Pass
General steering & handling	very good
Footbrake operation	Pass
Hand brake operation	Safe
Suspension noise	Pass
Road holding stability	Pass
Warning lights	Pass
Convenience	5 / 5 (100%)
Owners manual	Pass
	
Photo 74	
Service book & history	Yes
 	
Photo 75      Photo 76	
Keys remote controls & spare key	Yes

overall condition

2 / 2 (100%)

very good

diagnostic report

1 / 1 (100%)

Pass

Completion

**Additional Observations**

Test drive for 10 minutes and  
speed up to 70 mph

**Name & Signature of Vehicle Inspector**



16.12.2023 15:58 GMT