



Pre-delivery Inspection Checklist

Ys69usv / 1 Feb 2024 / Ford transit custom

Complete

Score	103 / 107 (96.26%)	Flagged items	0	Actions	0
Car Make/Model	Ford transit custom				
Vehicle Identification Number	Ys69usv				
Dealer	Reeds motors ltd				
Location	86 Welley Road Staines-Upon-Thames England TW19 5EP United Kingdom (51.46272513133572, -0.5614610524622026)				
Conducted on	01.02.2024 09:53 GMT				

Take photos of the vehicle from all sides



Photo 1



Photo 2



Photo 3



Photo 4

Odometer & chase number

Odometer reading

63886



Photo 5

chase number or photo



Photo 6

Body Exterior

6 / 6 (100%)

Glass

Safe




Photo 7




Photo 8

Door locks/operation

Pass

Fuel filler cover/petrol cap

Pass

General bodywork condition

very good

Corrosion

Pass

Outside mirrors

Pass



Photo 9




Photo 10

Wheels & Tires AND Brakes

10 / 12 (83.33%)

Front right tire

very good

Over 6mm



Photo 11



Photo 12




Photo 13




Photo 14



Photo 15

Front left tire

very good

Over 6mm




Photo 16




Photo 17




Photo 18




Photo 19




Photo 20

Rear left tire

very good

Over 5mm




Photo 21



Photo 22



Photo 23



Photo 24



Photo 25

Rear right tire

very good

Over 6mm




Photo 26



Photo 27



Photo 28




Photo 29




Photo 30

Spare tire

Pass



Photo 31

locking wheel nut

Pass



Photo 32

Discs & pads front




Photo 33

Discs & pad or Drums rear

Fluid leaks

Pass

Caliper and Wheel Cylinders

Pass

Pipes/unions & connections

Pass

Hand brake operation/adjustments

very good

Interior & Luggage Compartment

7 / 7 (100%)

Seat mechanism & Folding seats

Safe

Electrically Operated seats

N/A

Seat belts

Safe

Heated seats

Pass

Internal mirrors

N/A

Boot/tailgate lock

Safe

sun visor

Safe

Electrical Controls

15 / 15 (100%)

Ignition lock/starting system

Pass

Headlights

Pass



Photo 34



Photo 35



Photo 36

Side lights/running lights

Pass



Photo 37




Photo 38



Photo 39

Brake lights

Pass




Photo 40




Photo 41




Photo 42




Photo 43

Indicator & hazard lights

Pass

Reverse & fog lights

Pass

radio& CD player

Pass




Photo 44

Navigation System

N/A

Panel lights/dashboard illumination

Pass




Photo 45



Photo 46

Switches & controls

Pass



Photo 47



Photo 48



Photo 49




Photo 50



Photo 51

Instrument/controls function

Pass

Horn

Pass

Windows & sunroof operation

Pass

Wipers & jet washers

Good

Alarm & theft-Deterrent System

Pass

HEAT/VENT/AC/DEFOG/DEFROST

3 / 3 (100%)

Air Conditioning system

Yes

Heated system

Yes

Defog/Defrost

Yes

Engine Compartment

17 / 17 (100%)

Coolant level

Pass




Photo 52

Brake fluid level

Pass




Photo 53

Engine oil level

Pass





























Photo 54

Clutch fluid level	N/A
Power steering fluid level	Pass
Washer Fluid	Pass
Radiator & cap	Safe
Coolant leaks	Pass
   	
Hoses & pipes	Pass
Water pump	Pass
External engine leaks	Pass
     	
  	
Turbo/supercharger	Pass
Fuel pump & pipes	Safe
Drive belts	Pass
Cold starting	very good
Noise level when engine cold	very good

Excess fumes/smoke	Pass	
Clutch & Transmission	5 / 5 (100%)	
Fluid/oil leaks	Pass	
Linkages (check for signs of wear)	Pass	
Clutch test manual gearbox only	Pass	
Automatic gear selection test	N/A	
Bearings & supports	Pass	
all gear selection test	1 / 1 (100%)	
	Yes	
Exhaust System	4 / 4 (100%)	
manifold	Pass	
  		
Photo 68	Photo 69	Photo 70
Heat shields & mountings	Pass	
Catalytic converter	Pass	
Overall system condition	Pass	
Fuel System	4 / 4 (100%)	
Fuel Pump Noise Normal	Pass	
Fuel Pump Pressure	Pass	
Fuel Filter	Pass	
Evidence of leaks	Pass	
Suspension, Underframe & Steering	13 / 13 (100%)	
Engine underside leaks	Pass	
Steering joints & ball joints	Pass	

Steering rack	Pass				
Chassis members	Pass				
Power steering Pump	Pass				
Wheels, hubs & bearings	Pass				
Springs & suspension unit	Pass				
Front suspension & Bushes overall	very good				
     					
Photo 71	Photo 72	Photo 73	Photo 74	Photo 75	Photo 76
Rear Suspension & bushes overall	very good				
  					
Photo 77	Photo 78	Photo 79			
Gaiters	Pass				
Sub frames & mountings	Pass				
Suspension arms, mountings & fixings	Pass				
Tie bars & anti-roll bars	Pass				
Road Test	15 / 15 (100%)				
Road Test 1	15 / 15 (100%)				
Engine - performance	very good				
Engine - noise	Safe				
Engine - excessive fumes or smoke	Pass				
Evidence of overheating	Pass				
Gearbox operation & noise level	Pass				

Final drive operation & noise level	Pass
Clutch operation	Pass
Cooling fan operation	Pass
Instruments & controls functioning	Pass
General steering & handling	very good
Footbrake operation	Pass
Hand brake operation	Safe
Suspension noise	Pass
Road holding stability	Pass
Warning lights	Pass
Convenience	3 / 5 (60%)
Owners manual	N/A
Service book & history	Yes
Keys remote controls & spare key	Yes
overall condition	0 / 2 (0%)
diagnostic report	0 / 1 (0%)

Completion

Additional Observations

Test drive for 10 minutes and speed up to 70 mph

Name & Signature of Vehicle Inspector



M and k
01.02.2024 10:22 GMT

Media summary



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7




Photo 8



Photo 9



Photo 10



Photo 11



Photo 12



Photo 13



Photo 14



Photo 15



Photo 16



Photo 17



Photo 18



Photo 19



Photo 20



Photo 21



Photo 22



Photo 23



Photo 24



Photo 25



Photo 26



Photo 27



Photo 28



Photo 29



Photo 30



Photo 31



Photo 32



Photo 33



Photo 34



Photo 35



Photo 36



Photo 37



Photo 38



Photo 39



Photo 40



Photo 41



Photo 42



Photo 43



Photo 44



Photo 45



Photo 46



Photo 47



Photo 48



Photo 49



Photo 50



Photo 51



Photo 52



Photo 53



Photo 54



Photo 55



Photo 56



Photo 57



Photo 58



Photo 59




Photo 60



Photo 61




Photo 62




Photo 63



Photo 64



Photo 65



Photo 66



Photo 67



Photo 68



Photo 69



Photo 70



Photo 71




Photo 72



Photo 73



Photo 74



Photo 75



Photo 76



Photo 77



Photo 78



Photo 79