



Pre-delivery Inspection Checklist

Lf65cjx / 2 Feb 2024 / Vw polo

Complete

Score	92 / 92 (100%)	Flagged items	0	Actions	0
Car Make/Model	Vw polo				
Vehicle Identification Number	Lf65cjx				
Dealer	Reeds motors ltd				
Location	86 Welley Road Staines-Upon-Thames England TW19 5EP United Kingdom (51.46272356657587, -0.5614616253560636)				
Conducted on	02.02.2024 09:06 GMT				

Take photos of the vehicle from all sides



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6

Odometer & chase number

Odometer reading

44016



Photo 7

chase number or photo



Photo 8

Body Exterior

6 / 6 (100%)

Glass

Safe

Door locks/operation

Pass

Fuel filler cover/petrol cap

Pass



Photo 9

General bodywork condition

very good

Corrosion

Pass

Outside mirrors

Pass




Photo 10



Photo 11

Wheels & Tires AND Brakes

12 / 12 (100%)

Front right tire

excellent

Over 7mm



Photo 12



Photo 13



Photo 14




Photo 15



Photo 16

Front left tire

Good

Over 4mm




Photo 17



Photo 18




Photo 19



Photo 20




Photo 21




Photo 22

Rear left tire

Good

Over 4.5mm




Photo 23



Photo 24



Photo 25



Photo 26

Rear right tire

Good

Over 4.5 mm




Photo 27



Photo 28




Photo 29








Photo 30

Spare tire

Pass



Photo 31

locking wheel nut	N/A
Discs & pads front	Good
Over 70%	
Discs & pad or Drums rear	Good
Disc over 70% pad around 50%	
Fluid leaks	Pass
Caliper and Wheel Cylinders	Pass
Pipes/unions & connections	Pass
Hand brake operation/adjustments	very good
Interior & Luggage Compartment	7 / 7 (100%)
Seat mechanism & Folding seats	Safe
Electrically Operated seats	N/A
Seat belts	Safe
  	
Photo 32 Photo 33 Photo 34	
Heated seats	N/A
Internal mirrors	Safe
	
Photo 35	
Boot/tailgate lock	Safe

sun visor

Safe

Electrical Controls

15 / 15 (100%)

Ignition lock/starting system

Pass



Photo 36

Headlights

Pass



Photo 37



Photo 38

Side lights/running lights

Pass




Photo 39



Photo 40

Brake lights

Pass



Photo 41



Photo 42



Photo 43



Photo 44

Indicator & hazard lights

Pass

Reverse & fog lights

Pass

radio& CD player

Pass




Photo 45

Navigation System

N/A

Panel lights/dashboard illumination

Pass

Switches & controls

Pass



Photo 46



Photo 47



Photo 48



Photo 49




Photo 50



Photo 51



Photo 52



Photo 53

Instrument/controls function

Pass

Horn

Pass

Windows & sunroof operation

Pass

Wipers & jet washers

Good

Alarm & theft-Deterrent System

Pass

HEAT/VENT/AC/DEFOG/DEFROST

3 / 3 (100%)

Air Conditioning system

Yes

Heated system

Yes

Defog/Defrost

Yes

Engine Compartment

17 / 17 (100%)

Coolant level

Pass



Photo 54

Brake fluid level

Pass

Engine oil level

Pass




Photo 55

Clutch fluid level

N/A

Power steering fluid level

N/A

Washer Fluid

Pass

Radiator & cap

Safe

Coolant leaks

Pass



Photo 56




Photo 57




Photo 58



Photo 59

Hoses & pipes

Pass

Water pump

Pass

External engine leaks

Pass



Photo 60



Photo 61



Photo 62




Photo 63




Photo 64




Photo 65




Photo 66




Photo 67




Photo 68




Photo 69




Photo 70

Turbo/supercharger

Pass

Fuel pump & pipes

Safe

Drive belts





Pass

Cold starting

very good

Noise level when engine cold

very good

Excess fumes/smoke	Pass
Clutch & Transmission	5 / 5 (100%)
Fluid/oil leaks	Pass
Linkages (check for signs of wear)	Pass
Clutch test manual gearbox only	Pass
Automatic gear selection test	N/A
Bearings & supports	Pass
all gear selection test	1 / 1 (100%)
	Yes
Exhaust System	4 / 4 (100%)
manifold	Pass
	
Photo 71	
Heat shields & mountings	Pass
	
Photo 72	
	
Photo 73	
	
Photo 74	
Catalytic converter	Pass
Overall system condition	Pass
Fuel System	4 / 4 (100%)
Fuel Pump Noise Normal	Pass
Fuel Pump Pressure	Pass
Fuel Filter	Pass
Evidence of leaks	Pass

Suspension, Underframe & Steering

13 / 13 (100%)

Engine underside leaks

Pass

Under tray fitted



Photo 75

Steering joints & ball joints

Pass

Steering rack

Pass

Chassis members

Pass

Power steering Pump

Pass

Wheels, hubs & bearings

Pass

Springs & suspension unit

Pass

Front suspension & Bushes overall

very good



Photo 76




Photo 77




Photo 78




Photo 79




Photo 80



Photo 81

Rear Suspension & bushes overall

very good




Photo 82




Photo 83

Gaiters

Pass

Sub frames & mountings

Pass

Suspension arms, mountings & fixings

Pass

Tie bars & anti-roll bars

Pass

Convenience

5 / 5 (100%)

Owners manual

Pass



Photo 84

Service book & history

Yes



Photo 85



Photo 86




Photo 87



Photo 88




Photo 89




Photo 90




Photo 91




Photo 92




Photo 93




Photo 94




Photo 95




Photo 96




Photo 97

Keys remote controls & spare key

Yes

2 keys



Photo 98

overall condition

2 / 2 (100%)

very good

diagnostic report

1 / 1 (100%)

Pass

Completion

Additional Observations

Test drive for 10 minutes and speed up to 70 mph

Name & Signature of Vehicle Inspector



M and k
02.02.2024 09:27 GMT